Qty. Description Item 38"h Q918 Vertical Extrusion 1 1 2 38"h Q918 Vertical Extrusion

- 3 38"h Q918 Vertical Extrusion
- 4 38"h Q918 Vertical Extrusion
- 5 38"h Q918 Vertical Extrusion
- 6 1 38"h Q918 Vertical Extrusion
- 7 32.155"w Z45 Horizontal Extrusion

© 2023

- 8 32.155"w Z45 Horizontal Extrusion
- 9 32.155"w Z45 Horizontal Extrusion 1
- 10 32.155"w Z45 Horizontal Extrusion
- 11 15"w Z45 Horizontal Extrusion 1
- 12 15"w Z45 Horizontal Extrusion 1
- 13 15"w Z45 Horizontal Extrusion 1
- 14 15"w Z45 Horizontal Extrusion 1
- 15 15"w Z45 Horizontal Extrusion 1
- 16 1 15"w Z45 Horizontal Extrusion
- 17 1 32.155"w Z45 Horizontal Extrusion
- 18 32.155"w Z45 Horizontal Extrusion 1
- 19 1 32.155"w Z45 Horizontal Extrusion
- 20 32.155"w Z45 Horizontal Extrusion 1

16

2

20

Door

2 Door ---


12


18"h Shelf Supports 6

Infil



- 1) Assemble lower horizontals [7,9,11,13,15,17,19] between verticals [1,2,3,4,5,6].
- 2) Insert infills between verticals [1,2], [2,3], [3,4], [1,5].
- 3) Connect upper horizontals [8,10,12,14,16,18,20] between verticals [1,2,3,4,5,6].
- 4) Attach Doors between verticals [4,5], [5,6]. See Door Attachment detail.
- 5) Affix shelf supports to inside of counter assembly using Velcro; place shelf onto shelf supports.
- 6) Affix Sintra Panels to outside of assembly, using Velcro.
- 6) Attach Counter Top to top of assembly.








19

BACK VIEW



When assembled

FRONT VIEW



General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.


Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.


Disassembly

- For loss prevention, tighten all set screws and locks during disassembly.






Hex Tool - Essential for Assembly



Extrusion & Lock Connection



















MARNING

DO NOT USE POWER TOOLS

LADDERS OR LIFTS MAY BE REQUIRED

ALL CONNECTIONS MUST **BE TIGHTLY SECURED**